

1 Products affected


Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.		
SBU PG PUG Type						
02 005 115 0000001137	See list below	Power Entry Modules w/o Filters	CMF1 / CMF4			
02 005 115 0000001138	See list below	Power Entry Modules w/o Filters	CMF2 / CMF5			
02 005 115 0000001139	See list below	Power Entry Modules w/o Filters	CMF3 / CMF6			
*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)						

List of part numbers	affected			
CMF1.1011.12	CMF4.1031.12	CMF2.1111.12	CMF3.1032.12	CMF3.1114.12
CMF1.1031.12	CMF2.1011.12	CMF2.1131.12	CMF3.1033.12	CMF3.1132.12
CMF1.1111.12	CMF2.1015.11	CMF3.1012.12	CMF3.1034.12	CMF3.1132.121
CMF1.1131.12	CMF2.1015.12	CMF3.1013.12	CMF3.1112.12	CMF3.1133.12
CMF1 1131 121	CMF2 1031 12	CMF3 1014 12	CMF3 1113 12	CMF3 1134 12

2 Type of change

- Change of markings
- Change of quick connect terminal

3 Detailed description of change



4 Reason of change

- Standard update to UL/CSA 60320-1
- Quick connect terminal too close to the socket wall (Only applicable for part numbers CMF2.1015.11 and CMF2.1015.12)

Product Change Notification				PCN CMFx				
owner	creation date	release date	released by	change order no	rev	page	D40 027 640	
huberth	18.06.2019	09.07.2019	limachcl	2017851	Α	1 of 2	D10-037-610	



5 Release date

The change takes effect in ww30/2019 (Date code 1930 or higher on label) and lasts approx. 6 months depending on the variant. This change has no effect on the validity of the approval certificates.

6 Impact of change and recommended action

Form	Yes	Change of markings, change of quick connect terminals
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet CMF1/CMF4	
Data Sheet CMF2/CMF5	
Data Sheet CMF3/CMF6	

Product Change Notification				PCN CMFx				
owner	creation date	release date	released by	change order no	rev	page	D40 027 640	
huberth	18.06.2019	09.07.2019	limachcl	2017851	Α	2 of 2	D10-037-610	