



PTN No.:1018007

Shunichi Kawashima Manager
ATP Div.
LSI Production control Dept.
ROHM Co., Ltd.

1/20/2020

Notification of Product Discontinuance

Dear Valued Customer

This letter intends as a formal notification that ROHM Co., Ltd. is discontinuing the production of the following product. We acknowledge the obligation to promptly inform our customers of the intent to exit products to enable our customers the ability to prepare for alternatives and/or assist in our product portfolio renewal process.

It would be very appreciated if you could your reply by March 29, 2020. Your early reply in this regard would be very much appreciated.

Product category	Affected part number(s)	Suggested replacement product
IC	Please refer to the list below	None
<u>Reason for discontinuance</u> Due to aging Final test equipment, Rohm is unable to sustain manufacturing.		
<u>Product discontinuance date</u> May 31, 2020		
<u>Note</u> Lack of response by the customer after these 30 days constitutes acceptance of the change.		

RGTS222304·04·001

Part Number List:

BA3308FV-BZE2
BU4069UBF-BZE2
BU4069UBFV-BZE2
BA15532F-BZE2
BA15532F-E2
BA3308F-BZE2
BA3308F-E2
BA3308FV-E2
BA3430F-E2

BU4069UBF-E2
BU4069UBFV-E2
BU9816FV-E2
474AS2
48327-E2
AP-N152B-E2
BA1106FS-T1
BA15218F-DX
BA15218F-DXE2
BA15532F
BA3308F
BA3308FV-E1
BA6126F
BA6126F-E2
BA6235F
BA6302AF-BZE2
BA6302AF-E2
BA6529F-E2
BA6550FS-BZE2
BA6550FS-E2
BA6721AFP-YHAE2
BA823F-E2
BH3532FS-ME2
BU12005-01-VP
BU16503-07
BU3461-2D-E2
BU3461-2G-E2
BU3461-2H-E2
BU4069UBF
BU4069UBF-E1
BU4069UBFV-E1
BU5167KS-VP
BU5180CKV
BU6279AKU
BU6287KVT
BU6328KV
BU6495KU
BU6640AKU
BU6716KU
BU7611BKS
JCY0104
JCY0122
MT6364A
NN91044MA
R-2-7612-2