



EOL-STB-001042

Product Obsolescence Notification

Issue Date: August 15, 2018

Dear [CUSTOMER]:

Broadcom Inc. regrets to announce the obsolescence of the following products:

Broadcom Part Numbers	Description	LTB Date	LTS Date	Minimum Order (MOQ)	Suggested Replacement
7583UBKFEBAA3A1C	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
75848FPKFDBA3	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
75848FPKFEBAA3A0C	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM72325ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM72328ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75282ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75283ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75283ZZKFEB73G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75284ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75284ZZKFEB73G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75288ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7576ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75831APKFEBAA3G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below



BCM75831LPKFEB01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75831NCKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75831NCKFEB01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75831NCKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75831RBKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75831TCKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75831TPKFEB01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75831TPKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75831UBKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75831UPKFEB01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75831UPKFEB01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75831UPKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75831ZZKFEB01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75831ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75835NCKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75835TDKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75835TPKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below



		2018			
BCM75835ZSKFEB99G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75835ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75835ZZKFEB99G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75836MJKFEB01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75836ZBKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75836ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75838FDKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75838FPKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75838HCKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75838HPKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75838ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75839TDKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75839TPKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75839UPKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75839ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7583APKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below



BCM7583NCKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7583RBKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7583RPKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7583TDKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7583TPKFEBA01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7583TPKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7583UPKFEBA01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7583UPKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7583UPKFEBA73G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7583ZZKFEBO3G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7583ZZKFSB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75841APKFEBA3G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75841NCKFEBA3G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75841UPKFEBA1G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75841UPKFEBA3G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75841ZZKFEBO3G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75842LPKFEBA1G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below



		2018			
BCM75842NCKFEBA1G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75842NCKFEBA3G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75842RPKFEBA1G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75842TPKFEBA1G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75842UPKFEBA3G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75842ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75845NCKFEBA01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75845NCKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75845ZSKFEB99G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75845ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75846ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75848APKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75848NCKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75848RPKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75848TNKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75848TPKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below



BCM75848TSKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75848UPKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75848ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75849ZSKFEB99G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM75849ZZKFEB03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584APKFEBA01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584APKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584LPKFEBA01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584LPKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584NCKFEBA01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584NCKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584RDKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584RPKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584TCKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584TDKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584TNKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584TPKFEBA01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below



BCM7584TPKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584TSKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584UDKFEBA01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584UDKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584UPKFEBA01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584UPKFEBA03G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584ZBKFEBA01G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584ZZKFEBO1G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below
BCM7584ZZKFEBO3G	HD Cable STB IC	Aug. 31 st , 2018	Oct. 31 st , 2018	10,000	See below

The Pin-pin compatible replacement parts have been communicated in the document "PCN-STB-43125-028-0". The reason for this end-of-life announcement is that we are transitioning to TSMC as the foundry supplier to these part numbers. The TSMC based units are in mass production with the standard lead-time.

Please provide your Broadcom Inc. Sales Office with your lifetime Last Time Buy order requirements (LTB) for the above products no later than the date noted in the above table. These orders are non-cancelable, non-returnable and cannot be rescheduled. Orders received after the Last Time Buy order (LTB) date noted in the above table cannot be accepted.

The last requested delivery date for these orders may not be later than the LTS date noted in the above table. Due to inherent variations in yields, Broadcom Inc. reserves the right to ship up to 5% under the original last time buy quantity, and this quantity will fully satisfy Broadcom Inc.'s obligation to deliver that product under this last time buy agreement.

All last time buy orders must be placed based on Broadcom Inc.'s minimum order quantity requirements per the above table. All prior commitments regarding Broadcom Inc. minimum order requirements do not apply to last time buy orders. Broadcom Inc. reserves the right to limit last time buy quantities based on capacity and material availability.

Please contact your Broadcom Inc. field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.